PATENT NO.

: 7,120,287 B2

Page 1 of 4

APPLICATION NO.: 10/614917

DATED

: October 10, 2006

INVENTOR(S)

: Kevin Wilson and Ron Hjorth

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

On the title page:

In Item (63) titled Related U.S.

Application Data, 2nd line:

after "Apr. 5, 2002," insert --now Pat. No.

6,588,854,--

In the drawings:

In FIG. 4.

within the box identified by reference numeral

50, please change "Sh If" to --Shelf--

In FIG. 5A,

within the box identified by the right-hand lead

line extending from reference numeral 66, change "Unm rked Lead Fram s" to

-- Unmarked Lead Frames--

In FIG. 5B,

within the lowermost box, change "Store Carri

rs on Sh lf and Associate Carrier #s With Sh If" to --Store Carriers on Shelf and Associate

Carrier #s With Shelf--

COLUMN 1, LINE 9,

change "U.S. Pat. No. 6,588,584," to --U.S.

Pat. No. 6,588,854,--

Signed and Sealed this

Fifth Day of February, 2008

JON W. DUDAS Director of the United States Patent and Trademark Office

PATENT NO.

: 7,120,287 B2

Page 2 of 4

APPLICATION NO.: 10/614917

DATED

: October 10, 2006

INVENTOR(S)

: Kevin Wilson and Ron Hjorth

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Please replace FIG. 4 with the following replacement figure:




Fig. 4

PATENT NO. : 7,120,287 B2 Page 3 of 4

APPLICATION NO.: 10/614917 DATED


: October 10, 2006

INVENTOR(S)

: Kevin Wilson and Ron Hjorth

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Please replace FIG. 5A with the following replacement figure:



PATENT NO. : 7,120,287 B2 Page 4 of 4

APPLICATION NO.: 10/614917 **DATED**

: October 10, 2006

INVENTOR(S)

: Kevin Wilson and Ron Hjorth

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Please replace FIG. 5B with the following replacement figure:

